

Black Magic Design Mise à jour UltraScope 1.8.2

Écrit par Jean-Christophe Perney
Samedi, 29 Août 2015 22:04



Mise à jour UltraScope 1.8.2, cette mise à jour logicielle permet d'utiliser simultanément les logiciels UltraScope et Blackmagic Media Express. Elle offre également des améliorations relatives à la performance générale :

Welcome to the UltraScope Software : This software package allows you to set up and update your Blackmagic UltraScope to the latest software release for new features, bug fixes and other enhancements.

What's new in UltraScope 1.8.2 :

General performance and stability improvements

Ability to run UltraScope and Media Express simultaneously

Minimum system requirements for Mac OS X

- Mac OS X 10.10 Yosemite
- Mac OS X 10.9 Mavericks or later
- A suitable PCIe slot - PCIe x1 lane cards should work in any slot
- A suitable USB 3.0 port for use with Pocket UltraScope
- 4 GB of system memory recommended
- Note: UltraScope is not supported on Mac Pro G5 computers.

Minimum system requirements for Windows

- Microsoft Windows 8 64-bit
- Microsoft Windows 7 64-bit
- A suitable PCIe slot - PCIe x1 lane cards should work in any slot
- A suitable USB 3.0 port for use with Pocket UltraScope
- 4 GB of system memory recommended.
- Installing UltraScope Software
- Before installing the software, we recommend that you run "Uninstall UltraScope" first.

The Blackmagic Camera Installer package installs: Blackmagic UltraScope